

ATA AIRLINES, INC.

ALTERNATE FLAP DRIVE GEARBOX SERVICING

PAGE 1 / 1

CHECK BEING PERFORMED: Custom

ZONES: 100
A/C NUMBER:
REV. DATE: 01/23/06
FREQUENCY: 1C

W/C NUMBER: 317L2701 DATE:

MFR P/N	DESCRIPTION	QTY
M25988-1-012	Packing	1
MILH5606	Hydraulic Fluid	A/R

REFERENCES

Figures 1 and 2, AMM 27-51-00

MECH INSP

MPD Item: 27-178-00

1. Trailing Edge Flap Electric Motor Servicing (Figure 1).

_____ XXXXX A. Prepare for the Lubrication.

(1) Do this task: Trailing Edge Flap System Deactivation
(AMM TASK 27-51-00-040-801 p201).

_____ XXXXX B. Trailing Edge Flap Electric Motor Servicing.

(1) Do a check of the fluid level in the flap electric motor:

(a) Remove the fill plug [181] and packing [182] from the fill port.

(b) Make sure the fluid is at the level of the fill port.

(c) If the fluid is not at the level of the fill port, fill the flap electric motor with fluid, MIL-H-5606 to the level of the fill port.

(d) Lubricate the new packing [182] with fluid.

(e) Install the fill plug [181] and new packing [182] in the fill port.

(f) Install lockwire on the fill plug [181].

_____ XXXXX C. Put the Airplane Back to Its Usual Condition.

(1) Do this task: Trailing Edge Flap System Reactivation
(AMM TASK 27-51-00-440-801 p201).

*****END OF WORKCARD*****

REVISION DATE: 01/23/06

ATA AIRLINES, INC. B737-800 FLEET

W/C #: 317L2701

DATE WORK CARD COMPLETE ___/___/___



