

ATA AIRLINES, INC.

INTERNAL-STABILIZER TORSION BOX COMPARTMENT

PAGE 1 / 1

CHECK BEING PERFORMED: Custom

ZONES: 300
A/C NUMBER:
REV. DATE: 01/23/06
FREQUENCY: S

W/C NUMBER: 331I5303 DATE:

PANELS

311BL
S3102

MECH INSP

|MPD ITEM: 55-020-00

STRUCTURES

INTERVAL NOTE:
Whichever comes first.

ACCESS PANELS NOTE:
Adjust stabilizer trim as required. Remove gap seal and rear spar sliding seal to inspect pivot fittings.

INTERNAL - GENERAL VISUAL: STABILIZER TORSION BOX COMPARTMENT

Inspect horizontal stabilizer center section front spar, rear spar, pivot fittings, and primary and secondary thrust beams.

*****END OF WORKCARD*****