

ZONES: 200 500  
 A/C NUMBER:  
 REV. DATE: 06/01/06  
 FREQUENCY: 8A

W/C NUMBER: 353I2703 DATE:

## REFERENCES

AMM 27-62-00

MECH INSP

| MPD ITEM: 27-215-01

PERFORM A GENERAL VISUAL INSPECTION OF THE LEFT WING  
 FLIGHT SPOILER AND SPEEDBRAKE ACTUATORS

NOTE: Work with Workcard 363I2703 if issued.

NOTE: If workcard is being worked in a Line Maintenance  
 environment, work with B737 Line Service Check  
 "Left/Right Wing" tasks.

| 1. FLIGHT SPOILER AND SPEED BRAKE ACTUATORS INSPECTION

\_\_\_\_\_ XXXXX A. Procedure

WARNING: MAKE SURE THAT PERSONS AND EQUIPMENT ARE CLEAR  
 OF ALL CONTROL SURFACES BEFORE YOU SUPPLY  
 HYDRAULIC POWER. AILERONS, RUDDERS, ELEVATORS,  
 FLAPS, SLATS, SPOILERS, LANDING GEAR, AND  
 THRUST REVERSERS CAN MOVE QUICKLY WHEN YOU  
 SUPPLY HYDRAULIC POWER. THIS CAN CAUSE INJURY  
 TO PERSONS AND DAMAGE TO EQUIPMENT.

- (1) Do this task: Speed Brake Hydraulic Systems A and B  
 Pressurization (AMM TASK 27-62-00-800-801 p201).
- (2) Move the speed brake lever from the DOWN position  
 to the UP position.
- (3) Do a general visual inspection of the flight spoiler  
 and the speed brake actuators.
- (4) Move the speed brake lever from the UP position to  
 the DOWN position.
- (5) Do this task: Put the Speed Brake Hydraulic systems  
 A and B Back to the Condition Before the  
 Pressurization (AMM TASK 27-62-00-840-801 p201).

\*\*\*\*\*END OF WORKCARD\*\*\*\*\*