

ATA AIRLINES, INC.

LUBRICATE LH ELEVATOR

PAGE 1 / 1

CHECK BEING PERFORMED: Custom

ZONES: 344
A/C NUMBER: 197
REV. DATE: 03/16/2000
FREQUENCY: H2

W/C NUMBER: 533L5506
DATE: 04/12/2006
W/O:
JAC CODE:



PANELS

| | | | | | | |
|-------|-------|-------|-------|-------|-------|-------|
| 318BL | 334EB | 334HB | 334MB | 334QB | 334TB | 334VB |
| 335AB | 335CB | | | | | |
| 334CB | 334FB | 334LB | 334PB | 334SB | 334UB | 334WB |
| 335BB | | | | | | |

REFERENCES

MM12-23-15 533L5506

| | |
|-------------|-------------|
| MECH | INSP |
|-------------|-------------|

_____ XXXXX 1 LUBRICATE ALL FITTINGS ON LH ELEVATOR HINGES AND DAMPERS.

_____ XXXXX 2 LUBRICATE AFT ELEVATOR DRIVE QUADRANT INSTALLATION.

_____ XXXXX 3 LUBRICATE LH HORIZONTAL STABILIZER PIVOT BEARING SUPPORT.

*****END OF WORKCARD*****