

ATA AIRLINES, INC.

REPLACE FILTER #1 OVERPRESSURE S/O VALVE

PAGE 1 / 1

CHECK BEING PERFORMED: Custom

ZONES: 511
A/C NUMBER:
REV. DATE: 04/02/01
FREQUENCY: H2

W/C NUMBER: 554M3603
DATE:
W/O:
JAC CODE:



MFR P/N	DESCRIPTION	QTY
69494J910	PACKING	1
727604-4	FILTER	1

TOOLS	DESCRIPTION	QTY
RAYTEK ST-4L	INFRARED THERMOMETER OR EQUIVALENT	1

PANELS
511LB

REFERENCES
MM36-11-41 554M3603

MECH INSP

_____ XXXXX 1 REPLACE #1 ENGINE OVERPRESSURE SHUTOFF VALVE FILTER AND "O"
| RING. PER MM 36-11-41 PB400.

_____ _____ 2 PERFORM A PNEUMATIC LEAK CHECK OF THE #1 ENGINE OVERPRESSURE
SHUTOFF VALVE.

NOTE: IF AVAILABLE, USE OF AN INFRARED THERMOMETER (RAYTEK ST-4L OR EQUIVALENT) IS RECOMMENDED TO AID IN THE DETECTION OF HOT AIR LEAKS.

*****END OF WORKCARD*****