

ATA AIRLINES, INC.

AD 1979-15-04 REPLACE NO 2 RIGHT SLAT CABLE

PAGE 1 / 1

CHECK BEING PERFORMED: Custom

ZONES:  
A/C NUMBER:  
REV. DATE: 06/07/07  
FREQUENCY: PCI  
AD NUMBER 1979-15-04  
MECH INSP

W/C NUMBER: 761R2701 DATE:

AD 79-15-04

REPLACE NO. 2 RIGHT SLAT CABLES

- \_\_\_\_\_ 1. Replace No. 2 right slat drive cables per DC10 AMM 20-20-07 and 91-11-05.

\*\*\*\*\* END OF WORKCARD \*\*\*\*\*