

ZONES: 725
A/C NUMBER:
REV. DATE: 06/07/07
FREQUENCY: PCI

W/C NUMBER: 774I3201 DATE:

MECH INSP

MRB 32-15-00-04

CENTERLINE LANDING GEAR PISTON INSPECTION

- XXXXX _____ 1. Check centerline landing gear piston for cracks using NDT procedures in accordance with Alert Bulletin A32-162 (Revision 2).

Note: *Discontinue foregoing special inspection after requirements in SB 32-160 and/or SB 32-189 have been accomplished.

Note: *Inspection intervals should be adjusted in accordance with inspection results and schedule in A32-162R2.

***** END OF WORKCARD *****