

**ATA AIRLINES, INC.**

INTERNAL-FORWARD PASSENGER COMPARTMENT FLOOR STRUCTURE-AREA DRY

PAGE 1 / 1

CHECK BEING PERFORMED: Custom

ZONES:

W/C NUMBER: 311I5306

DATE:

A/C NUMBER:

REV. DATE: 01/23/06

FREQUENCY: 6C

MECH        INSP

---

STRUCTURES

ACCESS PANELS NOTE:

Remove ceiling and sidewall panels as required. Remove/displace insulation blankets as required. Remove or displace auxiliary fuel tank as required (business jet only). Remove forward airstairs and airstairs compartment (if installed).

MPD ITEM:53-100-00

INTERNAL -GENERAL VISUAL: PASSENGER COMPARTMENT FLOOR STRUCTURE -DRY AREA

Inspect passenger compartment floor structure in dry areas (away from doors, galleys and lavs) from lower lobe.

\*\*\*\*\*END OF WORKCARD\*\*\*\*\*