

# ATA AIRLINES, INC.

VOICE RECORDER OPERATIONAL CHECK

PAGE 1 / 1

CHECK BEING PERFORMED: Custom

ZONES: 200  
A/C NUMBER:  
REV. DATE: 06/01/06  
FREQUENCY: 1A

W/C NUMBER: 321F2302 DATE:

## REFERENCES

AMM 23-51-00, 24-22-00

MECH INSP

---

MPD ITEM: 23-040-00

OPERATIONAL CHECK OF THE VOICE RECORDER.

|\_\_\_\_\_ XXXXX 1. VOICE RECORDER SYSTEM - OPERATIONAL TEST

### A. Prepare for the Test

- (1) Do this task: Supply Electrical Power  
(AMM TASK 24-22-00-860-811 p201).
- (2) Make sure that the Flight Interphone System is  
serviceable (AMM TASK 23-51-00-710-801 p501).
- (3) Connect a headset, H3310 to the voice recorder  
control panel at the pilot's overhead panel, P5.

### B. Operational Test

- (1) Do the Operational Test as follows:
  - (a) Push the TEST switch on the voice recorder control  
panel for approximately one half second.
    - 1) Make sure that you hear a tone in the headset,  
H3310.
    - 2) Make sure that the STATUS light comes on once.

### C. Put the Airplane Back to the Usual Condition

- (1) Remove the headset, H3310 from the voice recorder  
control panel.
- (2) Remove electrical power as required  
(AMM TASK 24-22-00-860-812 p201).

\*\*\*\*\* END OF WORKCARD \*\*\*\*\*

---

REVISION DATE: 06/01/06

ATA AIRLINES, INC. B737-800 FLEET

W/C #: 321F2302

DATE WORK CARD COMPLETE \_\_\_/\_\_\_/\_\_\_