

ZONES: 200 600
 A/C NUMBER:
 REV. DATE: 05/25/06
 FREQUENCY: 8A

W/C NUMBER: 363I2703 DATE:

REFERENCES

AMM 27-62-00

MECH INSP

MPD Item: 27-215-02

PERFORM A GENERAL VISUAL INSPECTION OF THE RIGHT WING
 FLIGHT SPOILER AND SPEEDBRAKE ACTUATORS

NOTE: Work with Workcard 353I2703 if issued.

NOTE: If workcard is being worked in a Line Maintenance
 environment, work with B737 Line Service Check
 "Left/Right Wing" tasks.

1. Flight Spoiler and Speed Brake Actuators Inspection

XXXXX A. Procedure

WARNING: MAKE SURE THAT PERSONS AND EQUIPMENT ARE CLEAR
 OF ALL CONTROL SURFACES BEFORE YOU SUPPLY
 HYDRAULIC POWER. AILERONS, RUDDERS, ELEVATORS,
 FLAPS, SLATS, SPOILERS, LANDING GEAR, AND
 THRUST REVERSERS CAN MOVE QUICKLY WHEN YOU
 SUPPLY HYDRAULIC POWER. THIS CAN CAUSE INJURY
 TO PERSONS AND DAMAGE TO EQUIPMENT.

- (1) Do this task: Speed Brake Hydraulic Systems A and B
 Pressurization (AMM TASK 27-62-00-800-801 p201).
- (2) Move the speed brake lever from the DOWN position
 to the UP position.
- (3) Do a general visual inspection of the flight spoiler
 and the speed brake actuators.
- (4) Move the speed brake lever from the UP position to
 the DOWN position.
- (5) Do this task: Put the Speed Brake Hydraulic systems
 A and B Back to the Condition Before the
 Pressurization (AMM TASK 27-62-00-840-801 p201).

*****END OF WORKCARD*****