

ATA AIRLINES, INC.

LUBRICATE RH ELEVATOR

PAGE 1 / 1

CHECK BEING PERFORMED: Custom

ZONES: 344
A/C NUMBER: 197
REV. DATE: 03/16/2000
FREQUENCY: H2

W/C NUMBER: 534L5501
DATE: 04/12/2006
W/O:
JAC CODE:



PANELS

318BR	334WB	344EB	344HB	344MB	344QB	344TB
345AB	345CB					
334VB	344CB	344FB	344LB	344PB	344SB	344UB
345BB						

REFERENCES

MM12-23-15 534L5501

MECH	INSP
-------------	-------------

_____ XXXXX 1 LUBRICATE ALL FITTINGS ON RH ELEVATOR HINGES AND DAMPERS.

_____ XXXXX 2 LUBRICATE AFT ELEVATOR DRIVE QUADRANT INSTALLATION.

_____ XXXXX 3 LUBRICATE RH HORIZONTAL STABILIZER PIVOT BEARING SUPPORT.

*****END OF WORKCARD*****