

ATA AIRLINES, INC.

CHECK TURBINE/ EXHAUST O-BOARD FUEL DRAINS: # 3 ENGINE

PAGE 1 / 1

CHECK BEING PERFORMED: Custom

ZONES: 420  
A/C NUMBER:  
REV. DATE: 03/16/00  
FREQUENCY: H1

W/C NUMBER: 543M7301  
DATE:  
W/O:  
JAC CODE:



PANELS

427A

REFERENCES

MM71-70-02 543M7301

MECH INSP

- 
- \_\_\_\_\_ XXXXX 1 LOCATE LOWER TURBINE FAIRING DRAIN HOLE
  
  - \_\_\_\_\_ XXXXX 2 CLEAR ANY CARBON FROM THE DRAIN TUBE AT THE DRAIN HOLE USING A  
5/16" DRILL BIT (USE HAND TWIST MOTION ONLY)
  
  - \_\_\_\_\_ XXXXX 3 POUR 2-4 LITERS OF WATER INTO THE ENGINE TURBINE EXHAUST DUCT.  
IF WATER DRAINS FREELY, RECORD "N/A" IN STEPS 4 THROUGH 6. IF  
WATER DOES NOT DRAIN FREELY, GO TO STEP 4.
  
  - \_\_\_\_\_ XXXXX 4 REMOVE PANEL 427A (IF NOT ALREADY REMOVED), REMOVE THE TURBINE  
FAIRING AND DRAIN TUBE PER MM 71-70-02 AND CLEAN, USING WIRES  
AS CLEANING PROBES.
  
  - \_\_\_\_\_ XXXXX 5 REINSTALL DRAIN TUBE PER MM 71-70-02
  
  - \_\_\_\_\_ XXXXX 6 POUR 2-4 LITERS OF WATER INTO THE ENGINE TURBINE EXHAUST DUCT.  
IF WATER DRAINS FREELY, NO FURTHER ACTION IS REQUIRED. IF  
WATER DOES NOT DRAIN FREELY, GO TO STEP 4.

\*\*\*\*\*END OF WORKCARD\*\*\*\*\*