

ATA AIRLINES, INC.

REPLACE IN-LINE HP FUEL FILTER: #3 ENGINE

PAGE 1 / 1

CHECK BEING PERFORMED: Custom

ZONES: 420
A/C NUMBER:
REV. DATE: 11/09/06
FREQUENCY: H2

W/C NUMBER: 543M7302
DATE: 12/20/06
W/O:
JAC CODE:



MFR P/N	DESCRIPTION	QTY
QA0816	FILTER	1
AS43013-126	RING, SEALING SB73-B357	1

PANELS

423A

REFERENCES

MM73-11-09 543M7302

MECH INSP

| _____ 1. (RII) REPLACE IN-LINE HP FUEL FILTER PER MM73-11-09 PB 411.

| NOTE: REFERENCE GMM CHAPTER 4 FOR SCOPE OF RII REQUIREMENTS.

NOTE: IF WORKCARD IS ACCOMPLISHED IN CONJUNCTION WITH A C-CHECK, ENSURE LEAK CHECK IS ENTERED ON WORKCARD 590I9901. IF NOT IN CONJUNCTION WITH A C-CHECK, SIGN-OFF INCLUDES LEAK CHECK.

*****END OF WORKCARD*****