

ATA AIRLINES, INC.

REPLACE FILTER #3 OVERPRESSURE S/O VALVE

PAGE 1 / 1

CHECK BEING PERFORMED: Custom

ZONES: 611  
A/C NUMBER:  
REV. DATE: 04/02/01  
FREQUENCY: H2

W/C NUMBER: 564M3603  
DATE:  
W/O:  
JAC CODE:



| MFR P/N   | DESCRIPTION | QTY |
|-----------|-------------|-----|
| 69494J910 | PACKING     | 1   |
| 727604-4  | FILTER      | 1   |

| TOOLS        | DESCRIPTION                        | QTY |
|--------------|------------------------------------|-----|
| RAYTEK ST-4L | INFRARED THERMOMETER OR EQUIVALENT | 1   |

PANELS

611LB

REFERENCES

MM36-11-41                      564M3603

MECH            INSP

\_\_\_\_\_ XXXXX 1 REPLACE #3 ENGINE OVERPRESSURE SHUTOFF VALVE FILTER AND "O"  
| RING. PER MM 36-11-41 PB400.

\_\_\_\_\_ 2 PERFORM A PNEUMATIC LEAK CHECK OF THE #3 OVERPRESSURE  
SHUTOFF VALVE.

NOTE: IF AVAILABLE, USE OF AN INFRARED THERMOMETER (RAYTEK  
ST-4L OR EQUIVALENT) IS RECOMMENDED TO AID IN THE  
DETECTION OF HOT AIR LEAKS.

\*\*\*\*\*END OF WORKCARD\*\*\*\*\*