

ATA AIRLINES, INC.

PSE 53.10.005E-LH FRAME to FLOOR STRUT INTERSECTION at LONGERON

PAGE 1 / 1

CHECK BEING PERFORMED: Custom

ZONES: 121 125 185

W/C NUMBER: 710I5303

DATE:

A/C NUMBER:

REV. DATE: 06/07/07

FREQUENCY: SID

AD NUMBER 2005-14-10

REFERENCES

DC-10 SID NDI Manual Section 2: 53-20-02

MECH INSP

AD 2005-14-10

XXXXX 1. Comply with PSE 53.10.005E, PSE 53.10.005E-LH FRAME to FLOOR
STRUT INTERSECTION at LONGERON 38, SID INSPECTION per DC-10
SID NDI Manual Section 2 53-20-02.

***** END OF WORKCARD *****