

ZONES: 181 182 185 186 W/C NUMBER: 712R2001 DATE:
 A/C NUMBER:
 REV. DATE: 06/07/07
 FREQUENCY: 4C

MECH INSP

MRB ITEM: 20-10-00-04

CLEAN CENTER AND AFT CARGO COMPARTMENT

- _____ XXXXX 1. Remove cargo linings.
- _____ _____ 2. In the Center and Aft Cargo Compartment Upper Tunnels and Under Side of Cabin Vents (Cusp Holes), clean area of dust, lint and all foreign objects; without disturbing any systems Installations.
- _____ XXXXX 3. Install cargo linings.

***** END OF WORKCARD *****