

ZONES: 151 152 153 154 W/C NUMBER: 212I5301 DATE:
 A/C NUMBER:
 REV. DATE: 09/20/07
 FREQUENCY: 1C

PANELS

1511 1541 822
 1531 1652

REFERENCES

E.O. 757-25NS-1909

MECH INSP

 AFT CARGO COMPARTMENT AND DOOR INSPECTIONS

NOTE: PANELS 1531 AND 1541 ARE BETWEEN BS 1260 - BS 1300

ZONES AFFECTED: 151, 152, 153, 154, 161, 162, 165, 166

A PERFORM THE FOLLOWING AFT CARGO DOOR INSPECTIONS.

XXXXX _____ 1 PERFORM EXTERNAL SURVEILLANCE OF THE AFT CARGO DOOR EXTERNAL SKIN, FRAME, AND LATCHES.

XXXXX _____ 2 PERFORM DETAILED EXTERNAL INSPECTION OF AFT CARGO CARGO DOOR STOPS AND ADJACENT FRAME.

B PERFORM THE FOLLOWING AFT CARGO COMPARTMENT INSPECTIONS.

XXXXX _____ 1 PERFORM EXTERNAL SURVEILLANCE OF THE AFT CARGO COMPARTMENT DOOR WITH THE DOOR OPENED.

XXXXX _____ 2 PERFORM INTERNAL SURVEILLANCE OF THE AFT CARGO COMPARTMENT INCLUDING AREAS BEHIND LEFT AND RIGHT SIDEWALL PANELS BETWEEN BS 1260 AND BS 1300.

XXXXX _____ 3 INSPECT THE AFT CARGO COMPARTMENT NETS FOR CONDITION AND SECURITY. THERE ARE THREE NETS: THE TRANSVERSE NET, THE SIDEWALL NET, AND THE DOOR NET (REF. E.O. 757-25NS-1909).

XXXXX _____ 4 PERFORM INTERNAL SURVEILLANCE OF THE AREAS FORWARD OF THE AFT CARGO COMPARTMENT.

XXXXX _____ 5 PERFORM INTERNAL SURVEILLANCE OF THE BULK CARGO COMPARTMENT WITHOUT REMOVING SIDEWALL OR CEILING PANELS.

XXXXX _____ 6 PERFORM INTERNAL SURVEILLANCE OF THE AREAS AFT OF THE BULK CARGO COMPARTMENT.

XXXXX _____ 7 INSPECT THE VICINITY OF THE OUTFLOW VALVE AND THE AFT EQUIPMENT/LAVATORY/GALLEY VENTILATION FANS FOR EVIDENCE OF BLUE WATER CONTAMINATION. IF EVIDENCE OF BLUE WATER IS FOUND, GENERATE A NON-ROUTINE AND A FORM M99-38-01, LAVATORY SPILL INSPECTION SHEET.

AFT CARGO COMPARTMENT AND CARGO COMPARTMENT DOOR

PAGE:2 /2

A/C NUMBER:

CHECK BEING PERFORMED: Cust

W/C NUMBER: 212I5301 (continued)

MECH: INSP:

NOTE: BLUE STAINS INDICATE THAT LAV FLUID IS BEING DRAWN
INTO THE LAVATORY VENT SYSTEM.

*****END OF WORKCARD*****