

ATA AIRLINES, INC.

MAIN EQUIPMENT CENTER AND ACCESS DOOR

PAGE 1 / 1

CHECK BEING PERFORMED: Custom

ZONES: 119 120
A/C NUMBER:
REV. DATE: 09/17/03
FREQUENCY: 1C

W/C NUMBER: 214I5301 DATE:
W/O:
JAC CODE:

PANELS

119BL

MECH INSP

MAIN EQUIPMENT CENTER AND ACCESS DOOR INSPECTION

| MPD Items :5300-100-03E
| 5300-100-04E
| 5240-119-01E
| 0600-119-01Z
| 0600-120-01Z

1. Perform the Following 119BL Access Door Inspections.

XXXXX _____ A. Perform External Surveillance of Main Equipment Center
access door (119BL) External skin, frame, hinges, latches
and stops.

XXXXX _____ B. Perform a Detailed External Inspection of the body
external skin within 12 inches of the access door
119BL cutout.

|XXXX _____ C. Perform a Detailed External Inspection of the door stops
and adjacent visible cutout structure within the aircraft
contour at access door 119BL.

2. Perform the Following Internal Surveillance Inspection.

XXXXX _____ A. Perform Internal Surveillance of the Main Equipment
Center.

*****END OF WORKCARD*****