

ATA AIRLINES, INC.

RIGHT MLG, DOORS, AND WHEELWELL

PAGE 1 / 1

CHECK BEING PERFORMED: Custom

ZONES: 143 144 731 740
A/C NUMBER:
REV. DATE: 12/21/04
FREQUENCY: 1A

W/C NUMBER: 273M3201 DATE:
W/O:
JAC CODE:

PANELS

1003

MECH INSP

PERFORM AN EXTERNAL GENERAL VISUAL INSPECTION OF THE FOLLOWING ZONES:

| ZONES AFFECTED: 144, 740, 741, 742, 743

| NOTE: If workcard is being worked in a Line Maintenance
| Environment, work with B757 Line Service Check
| "LANDING GEAR TASKS" section.

_____ XXXXX 1. Right main landing gear wheel well structure.

_____ XXXXX 2. Right main landing gear assembly.

_____ XXXXX 3. Right main landing gear doors.

*****END OF WORKCARD*****