

ATA AIRLINES, INC.

NO. 3 ENGINE CSD CHARGE AND SCAVENGE FILTER DIFFERENTIAL

PAGE 1 / 1

CHECK BEING PERFORMED: Custom

ZONES: 464

W/C NUMBER: 743I2401

DATE:

A/C NUMBER:

REV. DATE: 06/07/07

FREQUENCY: 1A

REFERENCES

AMM 71-00-00

MECH INSP

MRB ITEM: 24-00-00-01

VISUALLY INSPECT # 1 ENGINE CSD CHARGE AND SCAVENGE OIL FILTER
POP UP INDICATORS

_____ XXXXX 1. Open #3 engine cowlings per MM 71-00-00, p 201.

_____ XXXXX 2. Do a Detailed Visual Inspection of the CSD charge and
scavenge oil filter pop-up indicators for clogged filter
indication.

NOTE: If indicators have popped, filter elements should be
removed and contamination investigated, and elements
replaced.

_____ XXXXX 3. Close # 3 engine cowlings per MM 71-00-00, p 201.

***** END OF WORKCARD *****